

PB-117

## 5200 Series Stamp - Added Clinch Bead

Notice Date: August 3, 2016



### OVERVIEW

<b>Product</b>	5200 series
<b>Models Affected</b>	5250, 5251, 5283, 5216
<b>Effective Date</b>	September 27, 2016
<b>Overview</b>	All models in the 5200 series will include a clinch bead around the perimeter of the stamp.

### FEATURES & BENEFITS

<b>Appearance</b>	The addition of the clinch bead further enhances the carriage house stamp to provide more detail to the overall appearance of the door.
<b>Product Alignment</b>	Adding the clinch bead aligns the design with our 5900 series that has had the clinch bead since its introduction in 2010.
<b>Quality</b>	The clinch bead increases the stability of the section and the consistency of the stamps, increasing the overall quality of the section.

### LOGISTICS

<b>Timing</b>	The order cutoff on Monday, September 26 <sup>th</sup> will be the final cutoff using the original stamp. The new stamp will be standard for door orders dated September 27 <sup>th</sup> or later.
<b>Replacement Sections</b>	The original stamp will continue to be available as needed to balance inventory and to provide replacement sections for existing doors.
<b>Section Identification</b>	Sections with the new stamp will continue to be identified with the same model number to align with marketing material. Sections with the original stamp that are ordered after the September 26 <sup>th</sup> effective date will have a v added to the end of the model number. For example, a 5283 section with the original stamp will become a 5283v, indicating that it's from the original version.